

## MATERIAL SAFETY DATA SHEET

Date Printed: 02/16/2009

Date Updated: 02/03/2006

Version 1.2

---

Section 1 - Product and Company Information

---

Product Name	TRIZMA PRE-SET PH CRYSTALS REAGENT GRADE TRIZMA 8.0
Product Number	T4753
Brand	SIGMA
Company	Sigma-Aldrich
Address	3050 Spruce Street SAINT LOUIS MO 63103 US
Technical Phone:	800-325-5832
Fax:	800-325-5052
Emergency Phone:	314-776-6555

---

Section 2 - Composition/Information on Ingredient

---

Substance Name	CAS #
TRIZMA PRE-SET PH CRYSTALS REAGENT GRADE TRIZMA 8.0	None

---

Section 3 - Hazards Identification

---

## EMERGENCY OVERVIEW

Irritant.

Irritating to eyes, respiratory system and skin.

For additional information on toxicity, please refer to Section 11.

---

Section 4 - First Aid Measures

---

## ORAL EXPOSURE

If swallowed, wash out mouth with water provided person is conscious. Call a physician.

## INHALATION EXPOSURE

If inhaled, remove to fresh air. If breathing becomes difficult, call a physician.

## DERMAL EXPOSURE

In case of skin contact, flush with copious amounts of water for at least 15 minutes. Remove contaminated clothing and shoes. Call a physician.

## EYE EXPOSURE

In case of contact with eyes, flush with copious amounts of water for at least 15 minutes. Assure adequate flushing by separating the eyelids with fingers. Call a physician.

---

Section 5 - Fire Fighting Measures

---

## FLASH POINT

N/A

AUTOIGNITION TEMP  
N/A

FLAMMABILITY  
N/A

EXTINGUISHING MEDIA  
Suitable: Water spray. Carbon dioxide, dry chemical powder, or appropriate foam.

FIREFIGHTING  
Protective Equipment: Wear self-contained breathing apparatus and protective clothing to prevent contact with skin and eyes.  
Specific Hazard(s): Emits toxic fumes under fire conditions.

---

#### Section 6 - Accidental Release Measures

---

PROCEDURE(S) OF PERSONAL PRECAUTION(S)  
Wear respirator, chemical safety goggles, rubber boots, and heavy rubber gloves.

METHODS FOR CLEANING UP  
Sweep up, place in a bag and hold for waste disposal. Avoid raising dust. Ventilate area and wash spill site after material pickup is complete.

---

#### Section 7 - Handling and Storage

---

---

#### Section 8 - Exposure Controls / PPE

---

ENGINEERING CONTROLS  
Safety shower and eye bath. Mechanical exhaust required.

PERSONAL PROTECTIVE EQUIPMENT  
Respiratory: Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU). Where risk assessment shows air-purifying respirators are appropriate use a dust mask type N95 (US) or type P1 (EN 143) respirator.  
Hand: Compatible chemical-resistant gloves.  
Eye: Chemical safety goggles.

---

#### Section 9 - Physical/Chemical Properties

---

Appearance	Physical State: Solid	
Property	Value	At Temperature or Pressure
pH	N/A	
BP/BP Range	N/A	
MP/MP Range	N/A	
Freezing Point	N/A	
Vapor Pressure	N/A	
Vapor Density	N/A	
Saturated Vapor Conc.	N/A	
SG/Density	N/A	
Bulk Density	N/A	
Odor Threshold	N/A	
Volatile%	N/A	
VOC Content	N/A	

Water Content	N/A
Solvent Content	N/A
Evaporation Rate	N/A
Viscosity	N/A
Surface Tension	N/A
Partition Coefficient	N/A
Decomposition Temp.	N/A
Flash Point	N/A
Explosion Limits	N/A
Flammability	N/A
Autoignition Temp	N/A
Refractive Index	N/A
Optical Rotation	N/A
Miscellaneous Data	N/A
Solubility	N/A

N/A = not available

---

## Section 10 - Stability and Reactivity

---

### STABILITY

Materials to Avoid: Bases, Oxidizing agents.

### HAZARDOUS DECOMPOSITION PRODUCTS

Hazardous Decomposition Products: Carbon monoxide, carbon dioxide, and nitrogen oxides.

---

## Section 11 - Toxicological Information

---

### ROUTE OF EXPOSURE

Inhalation: Material is irritating to mucous membranes and upper respiratory tract.

Multiple Routes: Causes eye and skin irritation. May be harmful by inhalation, ingestion, or skin absorption.

---

## Section 12 - Ecological Information

---

No data available.

---

## Section 13 - Disposal Considerations

---

### APPROPRIATE METHOD OF DISPOSAL OF SUBSTANCE OR PREPARATION

The material should be ignited in the presence of sodium carbonate and slaked lime (calcium hydroxide). The substance should be mixed with vermiculite and then with the dry caustics, wrapped in paper and burned in a chemical incinerator equipped with an afterburner and scrubber. Observe all federal, state, and local environmental regulations.

---

## Section 14 - Transport Information

---

---

## Section 15 - Regulatory Information

---

### EU ADDITIONAL CLASSIFICATION

Symbol of Danger: Xi

Indication of Danger: Irritant.

R: 36/37/38

Risk Statements: Irritating to eyes, respiratory system and skin.

S: 26-36

Safety Statements: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. Wear

suitable protective clothing.

US CLASSIFICATION AND LABEL TEXT

Indication of Danger: Irritant.

Risk Statements: Irritating to eyes, respiratory system and skin.

Safety Statements: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. Wear suitable protective clothing.

CANADA REGULATORY INFORMATION

WHMIS Classification: This product has been classified in accordance with the hazard criteria of the CPR, and the MSDS contains all the information required by the CPR.

DSL: No

NDSL: No

---

Section 16 - Other Information

---

DISCLAIMER

For R&D use only. Not for drug, household or other uses.

WARRANTY

The above information is believed to be correct but does not purport to be all inclusive and shall be used only as a guide. The information in this document is based on the present state of our knowledge and is applicable to the product with regard to appropriate safety precautions. It does not represent any guarantee of the properties of the product. Sigma-Aldrich Inc., shall not be held liable for any damage resulting from handling or from contact with the above product. See reverse side of invoice or packing slip for additional terms and conditions of sale. Copyright 2009 Sigma-Aldrich Co. License granted to make unlimited paper copies for internal use only.